

Care Instructions

For Foam Backed Fabrics (3 Pass Blackout Fabrics)

Standard Procedure for Dry Cleaning Foam Backed Material:

- Solvent: Perchloroethylene
- Cycle Time: 20 minutes maximum
- Temperature: Ambient temperature (room temperature)
- Solvent must be fresh.
- Remove solvent completely.
- Do not place in an extractor.

Standard Procedure for Laundering Foam Backed Material:

- Use delicate setting for washing.
- Set at lowest possible temperature.
- Use mild detergent. No bleach or additives.
- Tumble dry at delicate setting.
- Dry at lowest temperature setting.
- Do not exceed 100 degrees Fahrenheit.

Note:

Dry cleaning is the preferred procedure and is generally recommended. Foam products are designed to withstand up to three dry cleaning or laundering applications, BUT the procedures are mutually exclusive. Alternating these procedures will cause damage to the fabric. Once laundered, the item may NOT be dry cleaned. Once dry cleaned, the item may NOT be laundered.